

PHOTO INDEX



Photo showing the removed sill and lintel from the north elevation of the meeting hall.



Photo showing asphalt cut into sections for easier removal.



Photo showing workmen removing the asphalt course from the basement.



Photo showing equipment operator stockpiling asphalt for removal from site.



Photo showing stockpiled asphalt.



Photo showing workman prepping the area for the foundation excavation at the south side of the meeting hall.



Photo showing area for the foundation excavation.



Photo showing catch basin drain pipe in place for connection to the street.



Photo showing carpenter in the process of installing bridging and blocking for the 1st floor framing.



Photo showing a portion of the bridging and blocking in place.



Photo showing bridging and blocking in place at the ends of the joists.



Photo showing HVAC workman setting up to install ductwork outside of the platform.



Photo showing ductwork installed outside of the platform.



Photo showing ductwork assembly in place in the attic.