

PHOTO INDEX



Photo showing the stud wall framing for the Clerk's office.



Photo showing some stud wall framing in place on the 1st floor. This is looking northeast in the Clerk's office.



Photo showing stud wall framing in place on the 1st floor.



Photo showing carpenter working on the stud wall framing for the south end of the platform at the west end of the meeting hall.



Photo showing stud wall framing of south end of platform.



Photo showing carpenter installing blocking for a window mock-up in the meeting hall. This is on the north elevation.



Photo showing carpenter installing furring on the 2nd floor ceiling.



Photo showing carpenter installing rough wiring on the 2nd floor.



Photo showing rough wiring for surface mounted light fixtures.



Photo showing plumbers working on the 2nd floor bathroom.




Photo showing plumbing rough work in place.



Photo showing tin knocker assembling ductwork for installation.